Hornby Railways

4 - 6 - 2 LOCOMOTIVE CHASSIS - R.050, R.053, R.258

Most parts for R.053 as R.050

Magnadhesion is fitted to these models.

For motor see Service Sheet No. 81



X.52	Crosshead Assembly L/H
X.53	Crosshead Assembly R/H
X.66	Front Bogie (R.258)
X.236	Coupling Rod L/H
X.237	Coupling Rod R/H
X.297	Suppressor Unit
X.298	Brush Lead
X.335	Front Bogie (R.050)
X.391	Smoke Generator
X.443	Chassis Assembly
X.447	Collector Assembly
X.448	Driving Wheel – Black Tyre
X.448A	Driving Wheel – Plated Tyre
X.449	Bushed Wheel – Black Tyre
X.449A	Bushed Wheel – Plated Tyre
X.451A	Wheel with Crank – Plated
X.453	Pony Truck (R.050)
X.478	Flangeless Wheel – Black
X.505	Pony Truck (R.258)
X.549	Element
X.561	Element Contact and Lead
X.562	Piston Assembly
X.634	Valve Gear L/H (R.258)
X.635	Valve Gear R/H (R.258)
X.636	Cylinder Block Assembly (R.050)
X.636A	Cylinder Block Assembly (R.258)

X.637	Bogie Frame Assembly
X.735	Bogie Wheel (R.258)
X.736	Pony Truck Wheel (R.258)

S.1005	Gear Screw
S.1006	Bogie Screw
S.1010	Gear Screw (R.050)
S.1011	Screw
S.1090	Body Screw
S.1095	Pivot Screw
S.1101	Smoke Screw
S.2000	Knurled Axle
S.2001	Plain Axle

S.2002	Bogie Axle (R.050)
S.2014	Distance Piece
S.2129	Pony Truck Axle
S.2336	Bogie Axle (R.258)
S.3020	Drawbar
S.4020	Pony Truck Frame
S.4193	Cover Plate
S.4194	Smoke Unit Casting
S.5054	Bogie Wheel (R.050)
S.5056	Motion Bracket
S.6052	Pony Truck Wheel
S.6365	Worm Wheel
S.6850	Insulating Sleeve
S.6905	Fibre Wad

Modifications are made to models from time to time. If a spare part is required which does not coincide with the illustration, a full description should be given and, if necessary, a sketch or sample should accompany the order.

A4 – Printed in England.

ROVEX Limited
Westwood, Margate, Kent, CT9 4JX, England.

SERVICE SHEET No. 90
Issued June 1974
Supersedes Sheets Nos 59, 4a, 4, 3a, 3.