



LIST OF SPARES

| Item | Description | Pack | R2522 | R2523 |
|------|------------------------------|------|-------|-------|
| 1 | Motor Two Brass Flywheels | 1 | X9614 | X9614 |
| 2 | Main PCB Board | 1 | X9615 | X9615 |
| 3 | Lights Board | 1 | X9616 | X9616 |
| 4 | Motor Support | 1 | X9617 | X9617 |
| 5 | Gear Box Cover | 10 | X9618 | X9618 |
| 6 | Drive Unit | 1 | X9619 | X9619 |
| 7 | Bogies (no Wheels) | 2 | X9620 | X9620 |
| 8 | Worm Pinion / Shaft Assembly | 2 | X9621 | X9621 |
| 9 | Universal Shaft | 10 | X9622 | X9622 |
| 10 | Coupling Pack | 10 | X9623 | X9623 |
| 11 | Wheel Set Drive Unit | 4 | X9624 | X9624 |
| 12 | Assembly Pack | pack | X9625 | X9625 |
| 13 | Underframe | 1 | X9632 | X9633 |
| 14 | Snow Plough Pack (cut away) | 2 | X9626 | X9626 |