

OV∃X Service Centre

Albert Street, Ramsgate, Kent, CT11 9HD, England.

SERVICE SHEET No. 125



When reassembling ensure contrate gear


(S.9536) is on the correct side and that

wires from motor to guide blade are not

crossed.

See overleaf for list of spare parts

05967



to time. If a spere part is required which does

not coincide with the illustration, a full

description should be given and, if necessary,

a sketch or sample should accompany the

order.

W.1288

W.1289

L.5432

05967

Underpan.....

Drivers Head . .