



## SUPER 4 Y POINT-R.437



**NOTE:**  
 Super 4 Y Point R.437  
 may be converted for  
 electrical operation by  
 the addition of X.404  
 Point Motor.



- X.590** Blade Assembly
- X.648** Feed Strip and Insulator
- S.6400** Points Base
- S.6403** R. H Rail Short Curved

- S.6793** L/H Rail Short Curved
- S.6794** L/H Rail Curved
- S.6795** R/H Rail Curved
- ST.4048** Crank Lever Pivot Screw

- ST.4049** Crank Lever Pivot Nut
- ST.5158** Crank Lever R/H
- ST.5159** Crank Lever L/H
- ST.6030** Locking Spring

*Modifications are made to Tri-ang Hornby models from time to time. If a spare part is required which does not coincide with the illustration, a full description should be given and, if necessary, a sketch or sample should accompany the order. We do not undertake to supply separate components for the parts listed with an X prefix, unless a separate S part number is shown.*

PRINTED IN ENGLAND